IP7
0
374
基

CREW: 81	WORK ORDER TYPE: MODIF	ICATIONS		02-60456-55	ISSUE DATE 01/06/11	Pag	re 1 Of 2			
Originator	: PHILLIP HAILES	Schedule Date	: :		Date Completed:	F	allure Code:			
Planner	: RONALD TAYLOR	Priority	: 3A		•					
Drawing No	: 2SGA-M2063A	Clearance	; NO		Completed By :	S	ignature :			
Equip No/C	at: 2SGA3 0	Tag Request	:			· · · · · · · · · · · · · · · · · · ·	-			
Project ID	:	Text ID	:		Accepted By :	S	ignature :			
Shutdown	: U Unit	Frequency	: NOT	SCHEDULED						
Ref No	;	Last Reading	: No	Reading			** Delay Cod	es Legend **		
						W≈Whse	C=CrSp T=T	ag TL=Tool	P=Plan	
						** Re	cord Time Dai	ly **	Delays	
Step Job	Scope		MN D		cional Information	Emp No	Date	Hours	Code/Hrs	
	T 2 "OVER-FIRE CONTRACTO			1						
	R PHIL HAILES) FOR FABRI)							
FOR	OVERFIRE WINDBOX DUCT I	NSTALLATION.								
mo.	COLLED WINE AND MARRIAGE	MODIL DV (MDT)						****		
	COVER TIME AND MATERIALS									
	ESSARY FOR FABRICATION A									
	IFICATIONS REQUIRED FOR WINDBOX DUCT.	INE OVERFIRE								
AIR	WINDBOX DUCI.									
										
								-		
							<u></u>			
								-		
									-	
						** IMPORTANT NOTICE ** YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.				
Job Feedba	ck/Historical Notes:									



CREW: 81 WORK ORDER TYPE: MODIFICATIONS 02-60456-55 ISSUE DATE 01/06/11 Page 2 Of 2

** Work Order Parts List **							
Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1 DIRECT	SIGN, CUSTOM, DANGER, 14" X 20", ALUMINUM, TO READ: LINKAGES	04-38855	04/05/04	EA	4	0	4
2 DIRECT	SIGN, CUSTOM, DANGER, 7" X 10", ALUMINUM, TO READ: LINKAGES	04-38855	04/05/04	EA	8	0	8
3 DIRECT	LABEL, 3-1/2" X 5", EMEDCO P/N QS3475, 5/PK	04-38855	04/05/04	PK	2	0	2